

TBE

TBE-05-03-B

TBE-03-03-M

A = .325 [8.25] x No. of Poles + .728 [18.5]
 B = .325 [8.25] x (No. of Poles + .325 [8.25])

TBE

TBE-05-02-B

TBE-03-02-M

A = .325 [8.25] x No. of Poles + .728 [18.5]
 B = .325 [8.25] x (No. of Poles + .325 [8.25])

TBE

TBE-05-01-B

TBE-03-01-M

A = .325 [8.25] x No. of Poles + .728 [18.5]
 B = .325 [8.25] x (No. of Poles + .325 [8.25])