

DSP56303EVM

Advance Information DSP56303EVM Kit Contents List

The DSP56303 Evaluation Module (DSP56303EVM) kit contains:

- DSP56303 Evaluation Module board
- Four nylon standoffs and four nylon screws
- DSP56303EVM Kit Contents List (Order # DSP56303EVMCL/D)
- DSP56303EVM Product Information (Order # DSP56303EVMP/D)
- DSP56303EVM User's Manual (Order # DSP56303EMUM/AD)
- DSP56303 Chip Errata (Order # CHIPERRATA/D)
- Motorola Digital Signal Processor Registration Form (Order # DSPREGFORM/D)
- Crystal Semiconductor CS4215 16-Bit Multimedia Audio Codec Data Sheet
- Domain Technologies Debug-56K Debugger manual for Motorola's 16- and 24-bit DSPs
- GUI Debugger from Domain Technologies (3-1/2 inch diskette)
- One diskette (3-1/2 inch) containing demo software
- CD-ROM containing the Motorola Development Tools software and on-line User's Manual (DSPTOOLSCD—For orders please contact your local Motorola Sales office or authorized distributor)
- CD-ROM containing Motorola DSP Technical Documentation including the DSP56300 Family Manual, DSP56303 User's Manual, and DSP56303 Technical Data sheet (Order # CDDSP/D)

User Requirements

The user must provide the following:


- Power supply—7–9 V ac or dc with 2.1 mm receptacle (inside positive) power connector
- RS-232 cable (DB9 plug to DB9 receptacle)
- Audio source and a cable with 1/8-inch stereo plugs (needed for demonstration software only)
- IBM PC compatible computer (386 class or higher) running Windows 3.1 and DOS 6.0 (or higher), or Windows 95, with an RS-232 serial port capable of 9,600–56,600 bit-per-second operation, 4 Mbytes RAM, 3-1/2 inch diskette drive, hard drive with 4 Mbytes of free disk space, a mouse, and a CD-ROM drive

This document contains information on a new product. Specifications and information herein are subject to change without notice.

Mfax is a trademarks of Motorola, Inc.



© MOTOROLA, INC. 1997
Previous Printing 1996

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

How to reach us:

USA/Europe/Locations Not Listed:

Motorola Literature Distribution
P.O. Box 5405
Denver, Colorado 80217
1 (800) 441-2447
1 (303) 675-2140

Mfax™:

RMFAX0@email.sps.mot.com
TOUCHTONE (602) 244-6609
US & Canada ONLY
(800) 774-1848

Asia/Pacific:

Motorola Semiconductors H.K. Ltd.
8B Tai Ping Industrial Park
51 Ting Kok Road
Tai Po, N.T., Hong Kong
852-2662928

Technical Resource Center:

1 (800) 521-6274

DSP Helpline

dsphelp@dsp.sps.mot.com

Japan:

Nippon Motorola Ltd.
SPD, Strategic Planning Office
4-32-1, Nishi-Gotanda
Shinagawa-ku, Tokyo 141, Japan
81-3-5487-8488

Internet:

<http://www.motorola-dsp.com>



MOTOROLA