


3 • ROW Connectors

PC Card to
Board or
Chassis

WGA-WGA



Examples:

PLUG: WGA 122 PR9 SY
RECEPTACLE: WGA 122 SAC SY

PLUG

RECEPTACLE

SERIES

WGA = 3-row, right-angle, plug, mounting ears

WGA = 3-row, straight, receptacle, mounting ears
WGA = 3-row, right-angle, receptacle, mounting ears

NUMBER OF CONTACTS

122

122

TYPE OF CONTACTS

• The contact type determines image of connector. Pin right-angle contacts are always plug image, all other contacts, straight pin or sockets are receptacle image.

PR7 = Pin, right-angle, dip solder, .109
PR9 = Pin, right-angle, dip solder, .140
PR11 = Pin, right-angle, dip solder, .172
PRC = Pin, right-angle, solder cup
PRW32 = Pin, right-angle, wire wrap, .500

SAC = Socket, straight, solder cup
SAD7 = Socket, straight, dip solder, .109
SAD9 = Socket, straight, dip solder, .140
SAD11 = Socket, straight, dip solder, .172
SAF3 = Socket, straight, flex-circuit, .050
SAF6 = Socket, straight, flex-circuit, .093
SAF9 = Socket, straight, flex-circuit, .140
SAP = Socket, straight, pin termination, .150, connector saver
SAW24 = Socket, straight, wire wrap, .375
SAW40 = Socket, straight, wire wrap, .625
SOR7 = Socket, right-angle, dip solder, .109, see page W-51.
SOR9 = Socket, right-angle, dip solder, .140, see page W-51.
SOR11 = Socket, right-angle, dip solder, .172, see page W-51.

TYPE OF HARDWARE

• Turning hardware extends .040" shorter than normal.

SY = Guide Set
SY# = Guide Set, polarized
SYL = Guide Set, long
JT = Turning jackset, .435
JTA = Turning jackset, .135
JTB = Hex turning jackset, .135
JTC = Turning jackset, .435
JTL = Long turning jackset, .635

SY = Guide Set
SY# = Guide Set, polarized
SYL = Guide Set, long
J = Fixed jackset
JL = Fixed jackset, long

OPTIONS

• OPTION CODES: Add to the end of the part number. Example: WG160PR9SY548. Call factory for additional codes.
-B82: Termination face sealed against conformal coating.
-342: Remove .250 mounting ears.
-D01: Pre-tin contact terminations. (Solder cup, wire wrap and flex circuit contacts are excluded.)
-548: Includes nuts bonded into hex recess in mounting holes.
-G69: Solder cups are fixed in an outward orientation, otherwise contacts can rotate.
-413: Straight pin contacts in right-angle plug molding with solder cup terminals extending .100" beyond molding.
-D54: Combine B82 and D01 special codes.

